Contents

Preface xi

1 Introduction 1

1.1 The need for variable speed drives 1
1.2 Fundamental principles 2
1.3 Torque-speed curves for variable speed drives 7
1.4 Types of variable speed drives 11
1.5 Mechanical variable speed drive methods 13
1.5.1 Belt and chain drives with adjustable diameter sheaves 13
1.5.2 Metalic friction drives 14
1.6 Hydraulic variable speed drive methods 14
1.6.1 Hydrodynamic types 15
1.6.2 Hydrostatic type 15
1.7 Electromagnetic or 'Eddy Current' coupling 16
1.8 Electrical variable speed drive methods 20
1.8.1 AC commutator motor – schrage motor 20
1.8.2 Ward-Leonard system 20
1.8.3 Electrical variable speed drives for DC motors (DC drives) 21
1.8.4 Electrical variable speed drives for AC motors (AC drives) 23
1.8.5 Slip control AC variable speed drives 28
1.8.7 Cycloconverters 34
1.8.8 Servo-drives 34

2 3-phase AC induction motors 36

2.1 Introduction 36
2.2 Basic construction 37
2.2.1 The stator 37
2.2.2 The rotor 38
2.2.3 The other parts 38
2.3 Principles of operation 39
2.4 The equivalent circuit 41
2.5 Electrical and mechanical performance 45
2.6 Motor acceleration 48
2.7 AC induction generator performance 50
2.8 Efficiency of electric motors 51
2.9 Rating of AC induction motors 52
2.10 Electric motor duty cycles 54
S1: Continuous running duty 54
S2: Short-time duty 55
S3: Intermittent periodic duty not affected by the starting process 55

S4: Intermittent periodic duty affected by the starting process 56
S5: Intermittent periodic duty affected by the starting process and also by electric braking 57
S6: Continuous operation, periodic duty with intermittent load 58
S7: Uninterrupted periodic duty, affected by the starting process and also by electric braking 58
S8: Uninterrupted periodic duty with recurring speed and load changes 59
2.11 Cooling and ventilation of electric motors (IC) 60
2.12 Degree of protection of motor enclosures (IP) 62
2.13 Construction and mounting of AC induction motors 63
2.14 Anti-condensation heaters 65
2.15 Methods of starting AC induction motors 65
2.16 Motor selection 66

3 Power electronic converters 68

3.1 Introduction 68
3.2 Definitions 68
3.3 Power diodes 71
3.4 Power thyristors 73
3.5 Commutation 76
3.6 Power electronic rectifiers (AC/DC converters) 77
3.6.1 Line commutated diode rectifier bridge 81
3.6.2 The line commutated thyristor rectifier bridge 85
3.6.3 Practical limitations of line commutated converters 91
3.6.4 Applications for line commutated rectifiers 92
3.7 Gate commutated inverters (DC/AC converters) 94
3.7.1 Single-phase square wave inverter 95
3.7.2 Single-phase pulse width modulation (PWM) inverter 97
3.7.3 Three-phase inverter 101
3.8 Gate controlled power electronic devices 104
3.8.1 Gate turn-off thyristor (GTO) 104
3.8.2 Field controlled thyristors (FCT) 105
3.8.3 Power bipolar junction transistors (BJT) 105
3.8.4 Field effect transistor (FET) 108
3.8.5 Insulated gate bipolar transistor (IGBT) 109
3.8.6 Comparison of power ratings and switching speed of gate controlled power electronic devices 112
3.9 Other power converter circuit components 112

4 Electromagnetic compatibility (EMC) 114

4.1 Introduction 114
4.2 The sources of electromagnetic interference 116
4.3 Harmonics generated on the supply side of AC converters 118
4.3.1 Definitions 118
4.3.2 The analysis of the harmonic distortion 119

4.3.3 Effects of harmonics on other equipment 121
4.3.4 Acceptable levels of distortion in the mains supply system 126
4.3.5 Methods of reducing harmonic voltages in the power supply 127
4.4 Power factor and displacement factor 129
4.5 Voltages and current on the motor side of PWM inverters 131
4.5.1 Effect of the high PWM switching frequency on long motor cables 131
4.5.2 Selection of PWM switching frequency 132
4.5.3 High rates of rise of voltage (dv/dt) at inverter output 133
4.5.4 Protection of motors against high PWM switching frequency 135
4.5.5 Compliance with EMC standards 137
4.5.6 EMI (or RFI) filters for PWM inverters 138
4.5.7 Concluding comments about high PWM switching frequency 138

5 Protection of AC converters and motors 140

5.1 Introduction 140
5.2 AC frequency converter protection circuits 140
5.2.1 AC and DC under-voltage protection 141
5.2.2 AC and DC bus over-voltage protection 142
5.2.3 Output over-current protection 144
5.2.4 Output earthfault protection 146
5.2.5 Heat-sink over-temperature protection 147
5.2.6 Motor thermaloverload protection 147
5.2.7 Overall protection and diagnostics 148
5.3 Operator information and fault diagnostics 148
5.4 Electric motor protection 150
5.5 Thermal overload protection – current sensors 152
5.6 Thermal overload protection – direct temperature sensing 153

6 Control systems for AC variable speed drives 156

6.1 The overall control system 156
6.2 Power supply to the control system 157
6.3 The DC bus charging control system 159
6.4 The PWM rectifier for AC converters 161
6.5 Variable speed drive control loops 163
6.5.1 Open-loop control 163
6.5.2 Closed-loop control 163
6.5.3 Cascaded closed-loop control 165
6.6 Vector control for AC drives 167
6.6.1 Basic fixed V/f drives 170
6.6.2 V/f sensorless flux-vector drives (open loop vector) 171
6.6.3 Closed-loop field oriented vector drives 172
6.7 Current feedback in AC variable speed drives 174
6.7.1 Methods of measuring current in variable speed drives 174
6.7.2 Current feedback in general purpose VVVF drives 175

6.7.3 Current feedback in high performance vector drives 176
6.7.4 DC bus current feedback 176
6.8 Speed feedback from the motor 176

7 Selection of AC converters 178

7.1 Introduction 178
7.2 The basic selection procedure 179
7.3 The loadability of converter fed squirrel cage motors 180
7.4 Operation in the constant power region 183
7.5 The nature of the machine load 184
7.5.1 The load torque 184
7.5.2 Variable torque machine loads 187
7.5.3 Constant torque machine loads 187
7.5.4 The speed range 188
7.5.5 The inertia of the machine load 191
7.6 The requirements for starting 194
7.7 The requirements for stopping 196
7.7.1 DC injection braking 197
7.7.2 Motor over-flux braking 198
7.7.3 Dynamic braking 198
7.7.4 Regenerative braking 201
7.8 Control of speed, torque and accuracy 203
7.9 Selecting the correct size of motor and converter 203
7.10 Summary of the selection procedures 205
STEP 1. Specify the initial data for the drive application 205
STEP 2. Selecting the number of poles of the motor 205
STEP 3. Selecting the motor power rating 206
STEP 4. Select a suitable frequency converter 206
STEP 5. Final checks 207
STEP 6. An example of a selection calculation 207

8 Installation and commissioning 209

8.1 General installation and environmental requirements 209
8.1.1 General safety recommendations 209
8.1.2 Hazardous areas 210
8.1.3 Environmental conditions for installation 210
8.1.4 De-rating for high temperature 210
8.1.5 De-rating for high altitude 211
8.2 Power supply connections and earthing requirements 211
8.2.1 Power supply cables 212
8.2.2 Cables between converter and motor 213
8.2.3 Control cables 213
8.2.4 Earthing requirements 214
8.2.5 Common cabling errors 214

8.3 Start/stop control of AC drives 214
8.4 Installing AC converters into metal enclosures 216
8.4.1 Calculating the dimensions of the enclosure 217
8.4.2 Ventilation of enclosures 219
8.4.3 Alternative mounting arrangements 221
8.5 Control wiring for variable speed drives 222
8.5.1 Hard-wired connections to PLC control systems 223
8.5.2 Serial communications with PLC control systems 224
8.5.3 Interface converters 225
8.5.4 Local area networks 226
8.6 Commissioning variable speed drives 227
8.6.1 The purpose of commissioning 227
8.6.2 Selecting the correct application settings 227
8.6.3 Selecting the correct parameter settings 227

9 Special topics and new developments 229

9.1 Soft-switching 229
9.2 The matrix converter 231

Appendix A Motor protection – direct temperature sensing 233

Appendix B Current measurement transducers 244

Appendix C Speed measurement transducers 248

Appendix D International and national standards 262

Appendix E Glossary 266

Index 277