

Contents

Introduction	4
1 Outline of Welding Processes	5
2 Oxyfuel Gas Welding and Cutting	29
3 Arc Welding and Cutting	48
4 Personal Protective Equipment	63
5 Work on Vessels Contaminated by Hazardous Materials	74
6 Plasma Arc Processes	79
7 Electroslag Welding	82
8 Resistance Welding	84
9 Thermit Welding	89
10 Electron Beam Welding	93
11 Laser Welding and Cutting	99
12 Brazing and Braze Welding	105
13 Soft Soldering	115
14 Thermal Spraying	121
15 Welding and Flame Spraying Plastics	128
16 Radiographic Inspection	133
17 Mechanical Hazards	139
18 Measurement and Assessment of Fume	147
19 Sources of Fume	154
20 Ventilation and Fume Protection	171
21 Lighting	187
22 Fire	190
23 First Aid	200
24 US Health and Safety Legislation	204
Appendix 1 References	213
Appendix 2 American Standards, Specifications and Sources of Documents	223
Index	228