

Contents

Foreword.....	1
----------------------	----------

Section 1: Why is Monitoring Vibration Important? .. 2

What is Machine Vibration?	3
What Causes Machine Vibration?.....	5
(a) Repeating Forces	5
(b) Looseness	7
(c) Resonance.....	8
Why Monitor Machine Vibration?	10
(a) Severe Machine Damage.....	11
(b) High Power Consumption.....	12
(c) Machine Unavailability	12
(d) Delayed Shipments	13
(e) Accumulation of Unfinished Goods	13
(f) Unnecessary Maintenance.....	14
(g) Quality Problems	14
(h) Bad Company Image.....	15
(i) Occupational Hazards	15
Summary	16

Section 2: How is Machine Vibration Described? ... 17

How is Vibration Described?.....	18
What is Amplitude?	19
What is Frequency?	22
What is A Waveform?.....	23
What is A Spectrum?.....	24
Summary	26

Section 3: How is Machine Vibration Measured? 27

Which Machines Need Monitoring?	28
How Does the Instrument Work?	29
How is the Accelerometer Mounted?	30
(a) Mount as Close as Possible to the Bearing	31
(b) Make Sure the Accelerometer is Firmly Attached	32
(c) Make Sure the Accelerometer is Oriented Correctly	34
(d) Mount the Same Accelerometer in the Same Location.....	35
(e) Mount the Accelerometer on Something Substantial	35
(f) Take Care of the Accelerometer	36
(g) Take Care of Personal Safety	37
How are Parameters Set?	38
(a) How Data is Collected	39
(b) How Much or How Fast Data is Collected.....	40
What Fmax Value Should be Used?	41
How Many Spectral Lines Should be Used?	42
How Much Overlap Should I use?	42
(c) How Data is Processed	43
(d) How Data is Displayed	45
How is Data Collected?	48
Summary	54
Appendix: List of Symbols.....	55

Glossary Abbreviations Guide.....	57
--	-----------

Glossary of Terms.....	58
-------------------------------	-----------